

FIG. 1

20040309 011002




FIG. 2




FIG. 3





FIG. 4

FIG. 5








FIG. 7A FIG. 7B FIG. 7C FIG. 7D FIG. 7E FIG. 7F



2007-05-09 10:45:30

FIG. 8A FIG. 8B FIG. 8C FIG. 8D



Localization Uncertainty of 0.1 mm

Without Calibration




FIG. 9A

With Calibration




FIG. 9B

Localization Uncertainty of 0.5 mm

Without Calibration




Fig. 10A

With Calibration




Fig. 10B

20010"60254001

20070"6055400T

Localization Uncertainty of 1.0 mm

Without Calibration




Fig. 11A

With Calibration




Fig. 11B

FIG. 12




Fig. 13 A




Image result without SD calibration

Fig. 13B




Image result with SD calibration